2D Processing and Printing

2D Tool Bar

lcon	Description
	Box/Cursor
	Show Full spectra
	Zoom In Zoom Out Zoom Mode
__ _	Pan/Stretch Mode
<u></u>	Trace
	Scale
Į	Projections
Q	Redraw
5	Rotate
	Raise vertical scale by 20% Lower vertical scale by 20%
14	Phase Mode
	Peak Picking
0	Return

Manipulating the 2D data

Click on the appropriate icon on the tool bar to expand, zoom, and change the vertical scale of the spectra. Type dconi on the command line to display the peaks using the color map in the interactive mode. Type dpcon to display the peaks in contours. To show more contours than is automatically displayed, use a command that specifies the number of contours and spacing. To display this, **dpcon(20,1.3)** will display 20 contours at a spacing of 1.3. Other variations of this include **dpcon('pos',20,1.2)**. The modifiers 'pos' and 'neg' will display only the positive or only the negative peaks in a 2-D spectrum. To make the contour display interactive, use a variation of **dconi** such as **dconi('dpcon','pos',20,1.3)**. To plot more contours, **pcon(20,1.3) pltext page**. Adjust the number of contours and spacing for the data. The 'pos' and 'neg' modifiers can also be used in the plotting.

Processing 2D Data Sets Manually

This routine applies to most phase-sensitive 2-D data sets. COSY requires a slightly different approach and often uses a pure sinebell function.



Start by processing the first increment with by typing **wft(1)** Phase this spectrum as any 1-D.Then add a weighting function to this data by typing **wti** on the command line enabling the use of the interactive weighting screen to add a weighting function. The most commonly used function at this step is a gaussian function **[gf]**.



Then process the data with by typing **wft1da**. After the data is processed, the f1 traces will be on the screen. Select a trace with the cursor. Try to use something other than solvent. Then weight this trace with **wti**.



This weighting function can also be a gaussian function **[gf]**, but often a shifted sinebell is used. To put in a shifted sinebell, start with **[sb]** and move the cursor to produce a sinebell curve that is about twice the width of the interferogram. Then select **[sbs]**. Using the cursor, shift the sinebell back so the maximum starts at the left side of the interferogram. Process the 2-D data with >wft2da



Manual Phase Correction

Phase errors in phase-sensitive 2-D data sets can often be seen near the diagonal where the peaks may be streaked positive and negative. Display the entire 2-D spectrum. Choose 3 traces containing cross peaks near the top, middle and bottom of the spectrum and note the index #'s of each trace. The index # of the trace can be seen in the top window of VNMR next to the seq. and exp #.







Type **r1=***index***# r2=***index***# r3=***index***#** on the command line. The values r1-r3 are place holders in VNMR. Then display the first trace: Type **ds(r1) and** Phase

the 1-D trace. Display the 3^{rd} trace. **ds(r3)** Click \checkmark . Click the left mouse button on both sides of the spectrum to accept the previous phase changes. Then phase this trace. Go back to the first trace by typing **ds(r1)** Continue phasing r1 and r3, clicking to accept phase changes in-between until they are both phased. Look at the middle trace to check by typing **ds(r2)** Then go back to the 2-D

spectrum by typing **dconi**. If necessary, rotate the axis by clicking the *icon* and repeat the phase correction procedure.

Referencing the 2D Data

Place the cursor on the contour which you wish to use as your reference. If the spectra is homonuclear, then type rl(#p) rl1(#p) dconi. If the spectra is heteronuclear then type rl(#p) rl1(#d) dconi. Alternatively, the spectra can be referenced by filling in the reference boxes on the Default page of the Process Tab.

Start Acquire Pro	cess Transform Autoprocess	Display Spectrum Clear Screen	Cancel				
Basic Default Weighting Display More 2D Integration Cursors/Line Lists Plot Text Output	Transform FT 1D - 1st Increment Transform F2 Full 2D Transform FT Data Size Acq Pts P1 1k I28 P2 512 300 Transform Coefficients 1 0 0 0 0 0 - 10 Weighting: F1 gaussian F2 gaussian Save Current Process/Di	Display Display 2D Display Trace Projections Full Screen AutoScale 2D Trace ● F1 ● F2 Axis Display Mode F1 PPM ▼ Phased ▼ Linear Prediction ♥ F1 Auto LP F1 F2 F2 Auto LP F2 splay parameters In FID director	Display 1D # 424 Display Text BC Correct (F1, F2) DC Correct (F1, F2) DC Correct (F1, F2) Reference F1 by Solvent Potentie F2 by Solvent Set F1 cursor to: 0.00 H2 Set F2 cursor to: 0.00 Plot				

Place the cursor of the desired peak, set the units to ppm, enter the correct value into the boxes, enter on the keyboard, then redraw the spectra to observe the referenced spectra.

Weighting Display More 2D Integration Cursors/Line Lists Plot Text Output Transform F2 FU 2D Transform Display Trace Projections BC Correct Projections BC Correct Projections FT Data Size Plot Text Output Acq Pts Trace F1 F2 F1 1k 128 Trace F1 F2 F2 512 300 Axis Display Mode Reference F1 PHM F1 PPM Phased Set F1 cursor Set F1 cursor 100000-10 F1 PPM Phased Set F1 cursor Weighting: Linear Prediction F2 Auto LP F1 F2 Y F1 Auto LP F1 Set F2 cursor F2 Y F2 Auto LP F2 T10 Save Current Process/Display parameters In FID directory T10	t (F1, F2) t (F1, F2) t (F1, F2) t (F1, F2) t (Solvent t (Solvent t (Solvent t (Solvent t (Solvent t (Solvent t (Solvent t (Solvent) t (Solvent t (Solvent) t (Solvent t (Solvent) t (Solvent) t (Solvent t (Solvent) t (So
--	--



Plotting the 2D Data

The data can be easily plotted using the buttons on the Process >Basic page or the Process>Plot page. Choosing Plot Preview will allow the option of saving the file as a pdf, while choosing Plot Page will send the printout to the printer.

Default Weighting Display	sample: Solvent: dmso sample owner: vnmr1	Proce	ess Options	Plot Opt arameters: Ba	ions Isic -
More 2D Integration	Comments:	FT data size	e 🔄 💌]/	\
Cursors/Line Lists	STANDARD PROTON PARA	METERS 🛛 🗹 F1 linear	pred. <u>4*ni </u>	Plot 1D (F2): sp	ectrum 💌
Plot Tout Output		Weighting (F	2): gaussian <u>-</u>	(F1): <u>sp</u>	ectrum 💌
rext Output		Weighting (F	1): gaussian 💌	Plot	
	Display Spectru	m	rocess	Plot Pre	view
			save Current Pro	icess/Display scan	
Start Acquire Pro	cess Transform Au	oprocess Display Spe	ctrum Clear Scre	een Cancel	
Start Acquire Pro	Automatic Plot	oprocess Display Spe	ctrum Clear Scre	een Cancel Plot Pulse Sequence	1D Spectr sho
Start Acquire Pro Basic Default Weighting	Auto Plot Preview	oprocess Display Spe Contour Plot Positive sho	ctrum Clear Scre w plot Pa	een Cancel Plot Pulse Sequence arameters	1D Spectr she Plot Spectru
Start Acquire Pro Basic Default Weighting Display More 2D	Automatic Plot Auto Plot Preview Send this plot to march25 plot	Contour Plot Positive sho Negative sho Both sho	w plot Pa w plot Ba w plot	een Cancel Plot Pulse Sequence arameters sic Parameters Plot Parameters	1D Spectr shu Plot Spectru FID shu Plot FID S
Start Acquire Pro Basic Default Weighting Display More 2D Integration	Automatic Plot Auto Plot Preview Send this plot to march26_plot	Contour Plot Positive sho Negative sho Both sho Stacked Plot sho	ectrum Clear Scre w plot Pa w plot Ba w plot M	Plot Pulse Sequence rameters sist Parameters Plot Parameters isc	1D Spectr she Plot Spectrum FID she Plot FID S
Start Acquire Pro Basic Default Weighting Display More 2D Integration Eursors/Line Line Plot	Automatic Plot Auto Plot Preview Send this plot to march26_plot Plotter Type: B+W Creen Position	Contour Plot Positive sho Negative sho Both sho Stacked Plot sho Projection Hor	w plot w plot M	een Cancel Plot Puise Sequence arameters sic Parameters Plot Parameters isc Plot Text	1D Spectr shu Plot Spectru FID shu Plot FID S Clear P

Vert. plot

show plot • F1 • F2

6.0

Side Spectrum

Plot 2D Frequency List

Plot Molecules Plot Logo

Plot Page

Plot Preview

Left +x -x

 Right
 +y
 -y

 Center
 *x
 /x

Full *y /y

Projections

Trace

Trace Axis

Hz to mm: